Roof Condition Report

Polaris Expeditionary Learning School 1905 Orchard Place Fort Collins, Colorado

FOR

Ms. Tammie Knauer Poudre School District 2445 LaPorte Avenue Fort Collins, Colorado 80521

2016

Job Number: 8523-A



4155 E. Jewell Ave., Suite 414 Denver, CO 80222 (303) 329-0535 / (800) 266-8565 http://www.techniscan.com

Roof Composition:

Section A:

Deck Type: Wood Deck Insulation: 3" ISO., 1/2" Cover Board Roof Type: Built-Up Roof, Gravel Surface

Section B: Deck Type: Metal Insulation: 1.5" Perlite Roof Type: Built-Up Roof, Gravel Surface

Section C: Deck Type: Wood Insulation: 1.5" ISO., 1" Perlite Roof Type: 4-Ply Built-Up Roof, Gravel Surface

Section D: Deck Type: LW Concrete Insulation: 1.5" ISO., 1/2" Cover Board Roof Type: 4-Ply Built-Up Roof, Gravel Surface

Section F: Deck Type: Metal Insulation: 1" Wood Fiber Roof Type: Modified Bitumen, Smooth Surface

Section G: Metal Canopy

Section H: Deck Type: Metal Insulation: 4" ISO., 1/2" Cover Board Roof Type: Modified Bitumen, Granule Surface

Section : Deck Type: Wood Roof Type: Shingles

TechniScan, LLC

4155 East Jewell Avenue - Suite 414 303.329.0535 Phone

303.377.2740 Fax

Poudre School District

Polaris Expeditionary Learning 1905 Orchard Place Fort Collins, Colorado

| job no. | |
|-----------|------------|
| date | 06/14/2016 |
| drawn by | dls |
| Revisions | |
| 1 | |
| 2 | |
| 3 | |
| 4 | |
| 5 | |
| 6 | |
| 7 | |
| 8 | |
| 9 | |

NORTH

ROOF PLAN

Scale: 1/32" = 1'-0"

Roof

Plan

| Building Name | Polaris Expeditionary School |
|---------------------------|-------------------------------|
| Street Address | 1905 Orchard Place |
| Roof Section | Α |
| Square Footage | 23,195 |
| Roof Type | Built-Up Roof, Gravel Surface |
| Date Installed | 8/1/00 |
| Manufacturer | Unknown |
| Warranty Number | N/A |
| Warranty Expiration | N/A |
| Estimated Service Life | 7 years |
| Replacement Cost /sq ft | \$15.00 |
| 5-year Maintenance Budget | \$800 |
| | |

Notes: This roof area is still in good condition. The roofs were recommended for replacement in 2017 to have the entire building (excluding Section H) under one manufacturer warranty number and avoid additional mobilization costs and disruption in the future.

Photo 1



Roof Section A

Polaris Expeditionary Learning.

(09/12/2016 12:45:10 PM)

Photo 2



Built-up roof, gravel surface.

(09/12/2016 01:07:52 PM)



Photo 3



View of one of the skylights. The skylight has been repaired with caulking. It may be recommended that new skylights be installed during the roof replacement.

(09/12/2016 01:08:26 PM)

Photo 4




(09/12/2016 01:08:38 PM)

View of Section A.



Photo 5



The caulking on top of the reglet flashing is deteriorating. The reglet will be removed and a new surface-mounted counterflashing will be installed during the roof replacement.

(09/12/2016 01:10:12 PM)

Photo 6



View of the expansion joint. The expansion joint will be replaced during the roof replacement.

(09/12/2016 01:10:58 PM)

Photo 7



(09/12/2016 01:11:36 PM)

Photo 8



(09/12/2016 01:12:06 PM)

View of east area of Section A.



Photo 9



View of the east area of Section A looking south.

(09/12/2016 01:13:26 PM)

Photo 10



Overview of Section A. This is a new curb that was installed in the summer of 2016.

(09/12/2016 01:21:40 PM)



Photo 11



(09/12/2016 01:23:10 PM)

| Building Name | Polaris Expeditionary School |
|---------------------------|-------------------------------|
| Street Address | 1905 Orchard Place |
| Roof Section | В |
| Square Footage | 4,523 |
| Roof Type | Built-Up Roof, Gravel Surface |
| Date Installed | 8/1/93 |
| Manufacturer | Unknown |
| Warranty Number | N/A |
| Warranty Expiration | Expired |
| Estimated Service Life | 1 |
| Replacement Cost /sq ft | \$15.00 |
| 5-year Maintenance Budget | \$67,845 |
| | 1 61: 1 1:6 4 |

Notes: This roof has reached the end of its service life. A replacement is scheduled for 2017. A tear off to the deck is recommended for this roof.

Photo 1



Built-up roof, gravel surface.

(09/12/2016 01:13:52 PM)

Photo 2



View of Section B. This is located on the north side of the school. It is recommended the metal cap be replaced during the roof replacement.

(09/12/2016 01:16:04 PM)



Photo 3



(09/12/2016 01:16:32 PM)

10/11/2016 14:04:52 tempdbfpqxiqd0p.dbf (Copyright © 2016 TechniScan, LLC. All rights reserved.)

| Building Name | Polaris Expeditionary School |
|---------------------------|-------------------------------|
| Street Address | 1905 Orchard Place |
| Roof Section | С |
| Square Footage | 3,905 |
| Roof Type | Built-Up Roof, Gravel Surface |
| Date Installed | 8/1/89 |
| Manufacturer | Unknown |
| Warranty Number | N/A |
| Warranty Expiration | Expired |
| Estimated Service Life | 1 |
| Replacement Cost /sq ft | \$15.00 |
| 5-year Maintenance Budget | \$58,575 |
| | 1 (1) |

Notes: This roof has reached the end of its service life. A replacement is scheduled for 2017. A tear off of the existing roof is recommended for this roof.

Photo 1

Roof Section C

Gymnasium roof.



(09/12/2016 01:18:24 PM)

Photo 2



Open corner at a bell fan curb.

(09/12/2016 01:19:20 PM)

Photo 3



Caulking is deteriorating at the counterflashing.

(09/12/2016 01:19:30 PM)

Photo 4



(09/12/2016 01:19:54 PM)



Photo 5



Gymnasium roof, the caulking is cracking open in this corner.

(09/12/2016 01:23:54 PM)

| Building Name | Polaris Expeditionary School |
|---------------------------|-------------------------------|
| Street Address | 1905 Orchard Place |
| Roof Section | D |
| Square Footage | 11,692 |
| Roof Type | Built-Up Roof, Gravel Surface |
| Date Installed | 6/1/89 |
| Manufacturer | Unknown |
| Warranty Number | N/A |
| Warranty Expiration | Expired |
| Estimated Service Life | 1 |
| Replacement Cost /sq ft | \$15.00 |
| 5-year Maintenance Budget | \$175,380 |
| | 1 61: 116 4 |

Notes: The roof has reached the end of its service life. A replacement is scheduled for 2017. It is recommended this roof be torn off to the deck.

Photo 1



Roof Section D

Built-up roof, gravel surface.

(09/12/2016 01:26:40 PM)

Photo 2



north.

(09/12/2016 01:27:00 PM)

Photo 3



It is recommended that any obsolete penetrations be removed during the roof replacement.

(09/12/2016 01:27:12 PM)

Photo 4



North side of Section D. Smooth coat built-up roof.

(09/12/2016 01:28:10 PM)

| Building Name | Polaris Expeditionary School |
|---------------------------|-------------------------------|
| Street Address | 1905 Orchard Place |
| Roof Section | E |
| Square Footage | 2,291 |
| Roof Type | Built-Up Roof, Gravel Surface |
| Date Installed | 8/1/93 |
| Manufacturer | Unknown |
| Warranty Number | N/A |
| Warranty Expiration | Expired |
| Estimated Service Life | 1 year |
| Replacement Cost /sq ft | \$15.00 |
| 5-year Maintenance Budget | \$34,365 |
| | 1 61: 1 1:6 4 |

Notes: This roof has reached the end of its service life. A replacement is scheduled for 2017. It is recommended this roof be torn off to the deck.

Photo 1



Roof Section E

South end of Section E.

(09/12/2016 01:29:32 PM)

Photo 2



(09/12/2016 01:29:48 PM)

View of Section E looking west.

| Building Name | Polaris Expeditionary School |
|---------------------------|------------------------------|
| Street Address | 1905 Orchard Place |
| Roof Section | F |
| Square Footage | 2,946 |
| Roof Type | Modified Bitumen |
| Date Installed | 1/1/91 |
| Manufacturer | Unknown |
| Warranty Number | N/A |
| Warranty Expiration | Expired |
| Estimated Service Life | 1 |
| Replacement Cost /sq ft | \$12.00 |
| 5-year Maintenance Budget | \$35,352 |
| | 1 61. 116 4 |

Notes: The roof has reached the end of its service life. A replacement is scheduled for 2017. This roof will need to be torn off to the deck.

Photo 1



Roof Section F

View of Section F.

Built-up roof, gravel surface.

(09/12/2016 01:31:24 PM)

Photo 2



(09/12/2016 01:31:58 PM)



Another view of Section F. This area is recommended

Polaris Expeditionary Learning School - 1905 Orchard Place, Fort Collins, Colorado

Photo 3

(09/12/2016 01:32:02 PM)



| Building Name | Polaris Expeditionary School |
|---------------------------|------------------------------|
| Street Address | 1905 Orchard Place |
| Roof Section | G |
| Square Footage | 2,300 |
| Roof Type | Standing Seam Metal (Canopy) |
| Date Installed | Unknown |
| Manufacturer | Unknown |
| Warranty Number | N/A |
| Warranty Expiration | Expired |
| Estimated Service Life | 1 |
| Replacement Cost /sq ft | \$14.00 |
| 5-year Maintenance Budget | \$32,200 |

Notes: The roofs on the walk-way canopy have reached the end of their service life. A replacement is recommended in 2017. The replacement cost is based on an overlay over the existing roof. Approval from a structural engineer will be required for the proposed roof system.



Photo 1



Roof Section G

Metal canopy.

(09/12/2016 01:32:16 PM)

Photo 2



West area of the canopy looking north.

(09/12/2016 01:33:24 PM)

| Building Name | Polaris Expeditionary School |
|--|------------------------------|
| Street Address | 1905 Orchard Place |
| Roof Section | Н |
| Square Footage | 3,100 |
| Roof Type | Modifed Bitumen |
| Date Installed | 12/9/05 |
| Manufacturer | Johns Manville |
| Warranty Number | ANM111043881 |
| Warranty Expiration | 12/9/25 |
| Estimated Service Life | 9 years |
| Replacement Cost /sq ft | \$12.00 |
| 5-year Maintenance Budget | \$600 |
| Notes: These reads are in good condition. No repairs are | |

Notes: These roofs are in good condition. No repairs are recommended at this time.



Photo 1



Roof Section H

The roof is in good condition. No repairs are recommended.

(09/12/2016 01:20:26 PM)

Photo 2



View of Section H looking southeast. The roof is in good condition.

(09/12/2016 01:20:32 PM)

| Building Name | Polaris Epeditionary School |
|---------------------------|-----------------------------|
| Street Address | 1905 Orchard Place |
| Roof Section | I |
| Square Footage | 300 |
| Roof Type | Shingles |
| Date Installed | Unknown |
| Manufacturer | Unknown |
| Warranty Number | N/A |
| Warranty Expiration | N/A |
| Estimated Service Life | 1 |
| Replacement Cost /sq ft | \$8.50 |
| 5-year Maintenance Budget | \$2,550 |
| | |

Notes: The shingles have reached the end of their service life. A replacement is scheduled for 2017. When reroofed a single ply TPO roof is recommended.



Photo 1



Roof Section I

The shingles have reached the end of their service life. A single-ply roof system is recommended for this area.

(09/12/2016 01:35:40 PM)